294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series Technical File

SKU1: Z1L32940900340

SKU2: G1Y32940900340



SPLEEDE

SPLEINT

SPARA

19555

294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series

Technical File Steron, Sterond

SPARAC

STATIST

 ${\rm S}^{(0)}$

Content

Content Content
1. 294090-0340/294090-0350/294090-0360 Pump Plunger Introduction
1.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Basic Information2
1.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Common Part Number
1.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Parameter
1.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Specifications And Dimensions3
1.5. 294090-0340/294090-0350/294090-0360 Pump Plunger Quality Control
1.6. 294090-0340/294090-0350/294090-0360 Pump Plunger Customized Service
1.7. 294090-0340/294090-0350/294090-0360 Pump Plunger Packing List and Package Size
1.8. 294090-0340/294090-0350/294090-0360 Pump Plunger Testing Standard and Certificate5
1.9. 294090-0340/294090-0350/294090-0360 Pump Plunger Warranty Instructions
1.10. 294090-0340/294090-0350/294090-0360 Pump Plunger Manufacturer
2. 294090-0340/294090-0350/294090-0360 Pump Plunger Technical Support
2.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Installation
2.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Not Working Normally8
2.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Causes of Being Damaged8
2.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Technical Support Obtaining Methods9
3. 294090-0340/294090-0350/294090-0360 Pump Plunger Purchase and Delivery9
3.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Purchase Payment Term9
3.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Main Sales Markets9
3.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Declaration Requirements9
3.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Shipping Ways9
3.5. 294090-0340/294090-0350/294090-0360 Pump Plunger Lead Time
3.6. 294090-0340/294090-0350/294090-0360 Pump Plunger Logistics Time for Destination Out of
China's Areas10
3.7. 294090-0340/294090-0350/294090-0360 Pump Plunger Packing
4. 294090-0340/294090-0350/294090-0360 Pump Plunger Storage Standard
5. Company Information
5.1. Company Introduction
5.2. Salesmen's Contact Information13
6. Copyright Statement
. 20. 20. 20. 20. 20. 20. 20. 20. 20. 20
SHARAL SHERAL SH
appendance and appendance appendance appendance appendance appendance appendance appendance appendance appendance

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com

. and the

. and ^{the forest}

294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series

Technical File

1. 294090-0340/294090-0350/294090-0360 Pump Plunger Introduction

59.20 1.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Basic Information

Title	294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series	Quality
SKU1	Z1L32940900340	Remanufactured
SKU2 SKU2	G1Y32940900340	China Made New

1.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Common Part Number

(1) Pump Plunger Exchange Information

Pump Plunger	Pump Plunger Part Number	Universal Part Number	Universal Part Number	Universal Part Number
Pump Plunger 15	294090-0350	294090-0120	294090-0240	294090-0880
Pump Plunger 16	294090-0340	294090-0130	294090-0230	294090-0870
Pump Plunger 16	294090-0360	294090-0630	294090-0250	294090-0890

$\mathcal{F}_{\mathcal{D}_{\mathcal{D}}}$ (2) Pump Plunger Application Information

(2) Pump Plunger Application	on Information	TT OLIMAT OLIMAT OLIMAT	STREET, STREET, ST.
Oil Pump Part Number	OE Number	Vehicle Brand	Engine Number
294050-0027	8-97602049-3	STATIST' SPATIST' SPATIST	0310
294050-0423	8-97605946-6	The The The D	0905
294050-0102	8-98091565-0	ISUZU	0508
294050-0110	8-97605946-1	C. SPRIDALL SPRIDALL SPRIDAL	0606
294050-0123	8-97605106-1	the the the th	0610
294050-0130	22100-E0025	HINO State	0609
294050-0153	22100-E0101	The second second	0701
294050-0160	ME304718	MITSUBISHI	0705
294050-0172	ME306389	MITSUBISHI	0705
294050-0203	33100-52000	HYUNDA	0708

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd

and the

Tel: +8675523215133 Website : www.shumatt.com

and the second second

The The Trans. The Trans.

(3) Pump Plunger Common Writing 294090-0350, 294090-0120, 294090-0240, 294090-0880, 294090-0340, 294090-0130, 294090-0230, 294090-0870, 294090-0360, 294090-0630, 94090-0250, 294090-0890

1000 2. C. S. C. 1.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Parameter

Adaptation System: Common Rail System Pump Plunger Series: HP4 Series

- 655

Pump Plunger Type: High Pressure Common Rail Pump Plunger a Martin a starter ATT ATT ANT ANT ATT

1.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Specifications And Dimensions

Pump Plunger Size: 18cm* 13cm *11cm Pump Plunger Net Weight: 1900g Pump Plunger Gross Weight: 2000g Pump Plunger Quality: Remanufactured/China Made New Pump Plunger Package Size: 20cm* 15cm *13cm

Pump Plunger MOQ: 3 Pieces -38^{1,501} 3.³⁵

51^{9,519} 1.5. 294090-0340/294090-0350/294090-0360 Pump Plunger Quality Control REPARTS ARTIN REPERTY

(1) Pump Plunger Testing

- And State

 x^{0}

All pump plungers are tested for electrical characteristics, accuracy, high temperature, low temperature, withstand voltage, leakage, durability, and various working conditions.

(2) Pump Plunger Assembling

For the quality control of the pump plunger production and installation process, our company strictly follows the standard product installation data and product installation steps to install.

(3) Pump Plunger Inspection

The factory inspection of the pump plunger is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same pump plunger for more than three times for factory inspection, and the pump plunger installation testing environment are SHADER progressed in dust-free workshop.

1.6. 294090-0340/294090-0350/294090-0360 Pump Plunger Customized Service

(1) Pump Plunger Customized Service Coverage: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, pump plunger internal packaging, pump plunger external packaging and labels customized, etc.



Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd

(2) Pump Plunger Customized Service Requirements:

The quantity of customized pump plungers shall not be less than 10 pieces.

The quantity of customized pump plunger packages shall not be less than 1000 pieces.

. 2. C. S. S. S. When customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file. 10 C de. 100

A Once the customized pump plunger is sold, it cannot be returned or exchanged if there are no quality problems.

A. TERRER A TRUE A 2.325.55 0.578-57 A THERE ANT 2.577772.5 a start and Charles 1.7. 294090-0340/294090-0350/294090-0360 Pump Plunger Packing List and Package Size

(1) Pump Plunger Spare Parts List

(1) 1 011101		25. 25. 25. 25.	- AD - AD AD
No.	1	2	3
SAUDATT SA Image SAUDATT SA			
Name S	Pump Plunger	Bubble Bag	White Anti-rust Bag
Description	Pump plunger part number: 294090-0340/294090- 0350/294090-0360	Prevent the pump plunger from being damaged by external forces	Prevent pump plunger from rusting
No.	4	5	6
Surger St	The Street Street, Street, 2		and all all all all all all all all all al
softmage soft	anti si anti s	e de la companya de	States Streamer Virginies Str
SPALED TT SPA	STATE SALENCE SALENCE SALENCE S		STALL STRUCTURE STRUCTURES
Name	Desiccant	Pump Plunger Packing Box	The little the
0.01			00 x 00 x 00 x
Description	Prevent pump plunger from sture	Place the pump plunger and pump plunger accessories	The state

A Minors are prohibited from using the pump plunger assembly, O-rings, pump plunger housing covers, oil return covers, VCI anti-rust bags, and bubble bags to avoid personal injury.

🔺 The pump plunger housing cover and oil return cover are recyclable accessories and can be - call St A.S. $\infty^{h^{(p)}}$ recycled.

A VCI anti-rust bags and bubble bags are non-degradable materials. Please dispose of them properly after use. - STATE 1996 - 1997 T The The Atte

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd

🔺 The pump plunger and the installation parts guide tube should be treated with appropriate sealing Shith oil during installation. WEET. SPREED 0.55555 (2) Pump Plunger Box Size 2,55557 SPRETERT STATES SALTER S. C. S. S. $\mathcal{G}^{[0]}$ SPREAT STRUCTURE 59.205⁴ 58.50S 98.⁹⁸ $\mathcal{G}^{(0)}$ SPANSAT SPARAT 9.^{9,200} 19.5⁵³ SPAUDER SAUDET SILIDAT STA STORY 519.208.⁷ SPARAT REER 532.555 SPARAT 518.205T SHIPPE 39.99E N. $\varphi^{(0)}$ Pump Plunger Packing Size (cm) Name No. st^{ift} 91⁶³⁷ Stall **Pump Plunger Box** 20*15*13 1

1.8. 294090-0340/294090-0350/294090-0360 Pump Plunger Testing Standard and Certificate Shumatt can provide the factory quality inspection test report of each pump plunger to ensure that each pump plunger delivered meets the engine performance indicators.



Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2025 Shenzhen Shumatt Technology Co., Ltd



1.9. 294090-0340/294090-0350/294090-0360 Pump Plunger Warranty Instructions

25

(1) Product Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the pump plunger inspection equipment when the pump plunger is abnormal during use as evidence to feed back to the salesman. Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. oil leakage etc.

(2) Pump Plunger Warranty Coverage

 $\mathcal{D}_{\mathcal{D}_{\mathcal{D}}}$ act. Within 15 days after customer receives the 294090-0340/294090-0350/294090-0360 pump plunger, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair it;

If the 294090-0340/294090-0350/294090-0360 pump plunger has performance problems during the warranty period (6-12 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free:

If the pump plunger house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

Tips: For products not covered by warranty, our company can provide paid maintenance services. For products after paid repaired, the same performance problem will have a free warranty period within 3 months from the date of repairing.

(3) Pump Plunger Out of Warranty Coverage

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com $S^{(0)}$

1. The warranty period has expired. 2 Pump plunger failure caused by high temperature, high pressure, humidity, rain and snow, salinealkali land, earthquake, and used in abnormal environment.

Customer disassembles or repairs the pump plunger personally resulting in damage to the pump (3) plunger.

④ Pump plunger damage caused by man-made reasons (throwing, strong magnetic field 519.505 58^{9,50} SPRINT SANSE 37.50 magnetization, set fire).

⑤ Pump plunger failure or pump plunger damage caused by non-pump plunger design, technology, manufacturing, quality, and other issues.

6 Pump plunger failure due to system pressure exceeding system approved pressure.

⑦ Pump plunger failure caused by system voltage exceeding approved voltage.

8 Pump plunger failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

9 Pump plunger failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

1 Pump plunger failure caused by not following the installation angle specified in the vehicle engine S. S. Sta States Star Star -32¹⁵⁷¹ 3^{100} -19-²⁰⁰ maintenance manual.

11 Pump plunger failure caused by not following the cleaning requirements specified in the vehicle AND ST. ALTER ALTER -ALTERT ALTERT ALTERT engine maintenance manual.

12 Pump plunger failure caused by failure to replace consumable parts as specified in the vehicle engine maintenance manual. 55 - Co. a C 15 C 15 1 de 1 1 No.

13 Pump plunger failure caused by not complying with the intake system fit clearance and exhaust system fit clearance requirements specified in the vehicle engine maintenance manual.

14 Failure to replace the consumable parts and the fitting clearance of the oil inlet system pipeline and the pump plunger connection in accordance with the fuel intake system specified in the vehicle engine SPREAM maintenance manual. SPREATS

1.10. 294090-0340/294090-0350/294090-0360 Pump Plunger Manufacturer Pump Plunger Manufacturer: Shenzhen Shumatt Technology Co., Ltd

2. 294090-0340/294090-0350/294090-0360 Pump Plunger Technical Support

2.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Installation

(1) 294090-0340/294090-0350/294090-0360 Pump Plunger Installation Precautions:

 $\otimes^{2,2}$ -318-0 The replacement of the pump plunger must strictly follow the electrical system, the approved pressure of the low-pressure fuel intake system, the approved pressure of the high-pressure fuel circuit system, and fuel system replacement consumables requirements (including the low-pressure fuel circuit system filter and the high-pressure fuel circuit) specified in the vehicle engine maintenance manual. - And $S^{(n)}$ - 98⁴⁰

A Replacement of wearing parts of the fuel system, cleaning requirements for the connection between the fuel system and the pump plunger, the fitting clearance of the pump plunger connection, the installation angle and tightening torque of the pump plunger, the fitting clearance of the intake system, and the fitting clearance of the exhaust system to ensure the service life of the engine and the normal operation

A.S.

of the pump plunger. AL DON'T

9.50 FT A When installing the pump plunger on the engine, it is necessary to clean the engine block, cylinder

head and other parts connected to the pump plunger, and ensure that there is no dust, carbon deposits, water, rust spots, etc.

A When installing the pump plunger on the engine, please carefully check the components related to the installation of the pump plunger, such as the pump plunger pressure plate, screw, pump plunger rod and other accessories are not deformed, and install it in strict accordance with the operation steps of the engine maintenance manual.

It is forbidden to operate the bare pump plunger for a long time in an environment with serious dust pollution and corrosion to iron products.

1755 and i W. Part $\mathcal{O}_{\mathcal{O}_{\mathcal{O}}}$ 1⁹⁷⁵ -125 18 C It is forbidden to operate the bare pump plunger for a long time in a strong magnetic field

environment. zh^{ypn} -2015

2.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Not Working Normally SHUDD

- (1) There is air in the oil circuit of the engine fuel system.
- (2) Vehicle oil pump's oil supply system is not normal.
- (3) Engine common rail system oil leakage or pressure limiting valve damage.
- (4) There is a short circuit, cutting out and poor contact in the wiring harness connected to the pump plunger of the vehicle. 130 100 100
- (5) The long-term placement of the pump plunger causes the anti-rust oil to solidify, and the internal components are stuck or the oil holes are blocked.

100 100 1. San 100 . 18 C 18 C -18 C -1920 Before installing, carefully check whether other components in the common rail system except the

pump plunger are damaged to prevent the pump plunger from not working properly after being replaced. all spin de San - STATION - STATION - STATION - STATION - STATION 32.505

2.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Causes of Being Damaged

- (1) Didn't operate properly according to engine maintenance manual during disassembly or installation, resulting in damage to the pump plunger.
- (2) The fuel oil used for the vehicle does not meet the standard cause damage to the pump plunger, such as: the water content in the fuel oil exceeds the standard, iron powder, aluminum powder, sulfide and the impurities exceed the standard, etc. 18 C all^{er} -85°

(3) The engine is not regularly maintained according to the engine maintenance manual (please refer to the vehicle maintenance manual for the maintenance mileage). For example, failure to replace the lubricating oil of the engine system for a long time will cause abnormal wear of the engine, excessive exhaust gas volume or a large amount of carbon deposits inside the engine. The filter is not replaced

during maintenance or the replaced filter cannot reach the original filter standard. all above reasons can cause damage to the pump plunger.

(4) The abrasion of the pump plunger produces iron powder and aluminum powder enter the pump

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd

plunger and cause damage to the pump plunger.

- (5) The deformation and abrasion of fuel tank result in iron powder or aluminum powder entering the pump plunger and causing damage to the pump plunger.
- (6) The pump plunger is damaged due to replacement or adjustment of the relevant parts of the pump plunger. For example, the valve clearance does not meet the standard after the engine is repaired, the replacement or modification of the wiring harness connected to the pump plunger fails to meet the 27.500 ad for -33.200 al 3th A.M.
- original standard. a^{hF}
- (7) The engine is overheated and overloaded for a long-time working result in damage to the pump plunger, and a main a main a main a main a main a main a main
- (8) The pump plunger will be damaged naturally at the end of its working life.
- (9) The pump plunger is magnetized (pump plunger parts' magnetic exceeded) causing the pump plunger to not work properly. A.S.

A Before replacing the pump plunger, please check the engine parts carefully according to the engine maintenance manual to avoid the pump plunger being damaged again after replacement.

35 120 de la 12 100 2.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Technical Support Obtaining Methods

(1) Pump Plunger Technical File, visit http://shumatt.com to get the technical file.

(2) Pump Plunger Technical Videos

YouTube: https://www.youtube.com/channel/UCByvYBx7ViV mAfxh Hu-aw to get the technical videos, -13^{7,575} A ST constantly follow can get more information.

Shumatt: Visit <u>http://shumatt.com</u> to get the technical videos.

(3) Pump Plunger Information Query Software

4.50E TruckBook Parts EPC APP, Android/Apple App Store download and install, visit http://shumatt.com to get the download and installation tutorial 1200 100

1.500 T

(4) Search The fuel Pump Plunger test data through TruckBook Parts EPC APP.

3. 294090-0340/294090-0350/294090-0360 Pump Plunger Purchase and Delivery

3.1. 294090-0340/294090-0350/294090-0360 Pump Plunger Purchase Payment Term

Payment Terms: T/T, PayPal, Alipay, WeChat

Please **c**ontact our salesmen for specific payment information. SPLEENT SPERMIT TRUTTER' TRUTTER

SPRETERT SALDAN 3.2. 294090-0340/294090-0350/294090-0360 Pump Plunger Main Sales Markets

Pump Plunger Main Sales Markets: Asia, Europe, North America, South America, Africa etc.

3.3. 294090-0340/294090-0350/294090-0360 Pump Plunger Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

arrest. 2.200 1. 18 Mar 19 1 3.4. 294090-0340/294090-0350/294090-0360 Pump Plunger Shipping Ways

Destination in China Areas: SE-Express, Debon Express, the corresponding logistics company can be

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd

and a set a set

Tel: +8675523215133 Website : www.shumatt.com $\phi^{(i)}$

provided according to customer requirements in special cases. 100 Destinations Out of China's Areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers. 22.23.57

STATE STATE STATE STATE STATE STATE STATE 3.5. 294090-0340/294090-0350/294090-0360 Pump Plunger Lead Time

Lead Time: Send out within 3 - 7 working days after receiving payment (Except for special products and special cases). - STATE 30.50 - 034⁹⁰⁰

 $\mathcal{D}^{\mathbb{N}}$

3.6. 294090-0340/294090-0350/294090-0360 Pump Plunger Logistics Time for Destination Out of

China's Areas

DHL Logistics Time:

1.1

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries	ali.
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days	e ^{gi}

upper and the time of the second s

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK 🕬	5-7Days	Store Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5-7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal St	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar Qatar	7-10 Days	Poland	5-7 Days
Indonesia	3-5 Days	Morocco	7-10 Days	Pakistan	7-10 Days
Kuwait	7-10 Days	in the sec	1	5 . 13 . 13	~1 ×

The logistics time is for reference only and is subject to the actual arrival. N - N MARK SPERAL

ALENT CLEAR CLEAR ALEN 3.7. 294090-0340/294090-0350/294090-0360 Pump Plunger Packing

Domestic Express Packaging: Usually wrapped in waterproof scotch tape, such as picture No.15 International Express Packaging: Wrapped with waterproof yellow tape After wrapping the black protective

film, such as picture No. 2. The Tree with a tree with a tree the tree the tree the tree the tree and

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com

372.5357

 $S^{(i)}$

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 3, also, the products can be packaged according to customers' requirements.

SHORT SHADATT 155 -15 C 150 15 $\mathscr{G}^{(0)}$ The packing tray is made of plastic and can be recycled.

🔺 Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are State State non-degradable materials, please dispose of them properly.

and in 22 and the The The The The 17.80 See See Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film,

and white wrapping protective film to avoid personal injury. 100 1720



SPARA

Domestic express packaging: Wrapped with Transparent tape

International express packaging: $a^{b^{(j)}}$ Wrapped with yellow tape after wrapping black protective film



Pallet shipment: Use pallets that meet export requirements and wrap with white plastic wrap and tie. $\mathfrak{S}^{\mathbb{N}}$ 4. 294090-0340/294090-0350/294090-0360 Pump Plunger Storage Standard

e 19 -

(1) Choose a Suitable Storage Place

53 10 d Sa d 1 eC -The warehouse and cargo yard where the pump plunger is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acids, alkali, salt, and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry. and a state of the state of the

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2025 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com

1 S

(2) Strict Requirements of Warehousing

Strict inspections should be carried out when the pump plungers are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ashes, and other dirt, remove the rust and do anti-rust treatment in time. Packaged pump plungers must be protected from damage.

(3) Keep The Warehouse Dry And Preventing Moisture

The relative humidity is usually below 70% for the pump plungers placed in the room, and the corrosion of the pump plungers is significantly reduced.

Pump plungers must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the pump plunger is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the pump plunger from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse.

If the pump plunger package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

It is forbidden to leave the pump plunger exposed in the air for a long time.

It is forbidden to store acids, alkalis, salts, and other substances together with the pump plunger.





Chinese Name: 深圳市舒马特科技有限公司

English Name: Shenzhen Shumatt Technology Co., Ltd

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2025 Shenzhen Shumatt Technology Co., Ltd

Mob Phone/WeChat: +86-13410541523

HK Telephone: +852-67653519

Telephone: +86-755-23215133

Email: ruby@shumatt.com

Website: www.shumatt.com

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China's Mainland

Shenzhen Office: Exit C, Qiao Touxi Metro Station, NO. 66 Chongqing Road, Fuhai Avenue, Bao'an District, Shenzhen, China Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

• After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: <u>1.9. 294090-0340/294090-0350/294090-0360 Pump Plunger</u> Warranty Instructions)

5.2. Salesmen's Contact Information

No.	Name	WeChat/WhatsApp	Email
11	Ruby	+86-13410541523	ruby@shumatt.com
ahii 2 ahi	stor log stor	+86-18025299821	sales@shumatt.com
3	Rebecca	+86-18025349821	sales01@shumatt.com
a ³⁷⁴ .as	Janny	+86-18028749821	sales02@shumatt.com
5	Sam	+86-13316859821	Sales8@shumatt.com
	Natalie	+86- 18938945856	sales15@shumatt.com
7 37	Ada	+86-1342286353	sales5@shumatt.com
.8	Hison Li	+86-18318811871	web@shumatt.com
a ^{tu®} 9 at ^u	Mecca	+86-18938948618	sales11@shumatt.com
10	Eric	+86 18319033618	sales3@shumatt.com
3 ¹⁰⁷ 11 3 ¹⁰	Wayne (Joaquín en español)	+86-13316959821	wayne@shumatt.com
12	Sylvia	+86 18312499884	sales6@shumatt.com
store stor	Visit http://shumatt.co	om to obtain the latest informat	ion of salesmen
	PS: Shumatt's sales	men's emails are all end with @	shumatt.com
and the second	6° 46° 46° 49°	and the set of the set of the set	Staff all all all a

6. Copyright Statement

The copyright of any contents (including but not limited to parameters, data, text, charts, images,

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2025 Shenzhen Shumatt Technology Co., Ltd

sounds, or videos, etc.) provided in "294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series Technical File" in any way. At the same time, any conditions to spread, repost, display the contents of "294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "294090-0340/294090-0350/294090-0360 Pump Plunger HP4 Series Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.

58^{0,00} \wp^{p_i} Stoffer $\otimes^{[0]}$ STAIRS $\mathcal{G}_{\mathcal{C}}^{(i)}$ SANDET $\mathcal{G}_{\mathcal{C}}^{(0)}$ SHUMPI ze^{zeze} $\varphi^{0,i}$ SPUDE 51^{9,578} 31^{9,35} st^{ar}s $\wp^{(0)}$ STUDIES $\otimes^{[0]}$ States $\otimes^{[0]}$ SHURET STUR ps^{eek}

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2025 Shenzhen Shumatt Technology Co., Ltd