

F00RJ02130 Injector Valve Assembly Technical File



Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

F00RJ02130 Injector Valve Assembly Technical File

					00	1100110						
1. F00F	RJ02130 I L. F00RJ0	Injector \	/alve Ass	embly's I	ntroduct	ion	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	1	e e e e e e e e e e e e e e e e e e e	5	2
57 ⁽³⁾⁷⁴ .1	i. Foorjo 2. Foorjo)2130 In)2130 Ini	jector Va iector Va	ilve Asse Ive Asser	mbiy's Ba nbly's An	isic Infori plication	mation Informa	tion for Ir	 niectors .	907	S.A. 2011	2 2
1.3	3. F00RJ0)2130 Inj	ector Va	lve Asser	nbly's Sp	ecificatio	ns and D	imension	s Param	eters	d	6
1.4	4. F00RJ0)2130 lnj	ector Va	lve Asser	nbly's Qu	ality Con	trol					6
	5. F00RJ0 5. F00RJ0	-			-							
ر المراجعة 1.7 أنا المراجعة	7. F00RJC)2130 lnj	jector Va	lve Asser	nbly's Wa	arranty Ir	struction	าร				<i>7</i>
1.8	3. F00RJ0)2130 Inj	jector Va	lve Asser	nbly's Ma	anufactur	er					8
2. F00F	RJ02130	Injector \	/alve Ass	embly Te	chnical S	upport	زارسا در الأدراس		التين	5	j	8
	1. F00RJ0 2. F00RJ0											
	5. F00RJ0 RJ02130 v											
3. F00F	RJ02130 v	Valve Ass	embly's	Purchase	and Deli	very	- 150 mm	- 1967 1970 1970 1970 1970 1970 1970 1970 197	- 1910 · · · · · · · · · · · · · · · · · · ·	- S	- 1975.	10
3.1 -3.1	L. FOORJO Ž. FOORJO)2130 Va)2130 Va	ilve Asse Ive asser	mbly Pu nbly's M	rcnase P ain Sales	ayment I Market	erms	1		i	J	10 ් 10
3.3	3. F00RJ0)2130 Va	lve asser	nbly's De	eclaration	n Require	ements	.300	.36			10
3.4	4. F00RJ0 5. F00RJ0)2130 Va	lve Asser	mbly's Sh	ipping W	/ays					-6	10
3.5	5. FOORJO 5. FOORJO)2130 Va)2130 Va	Ive Asser	mbly's Le mbly's Le	ad Time ogistics T	ime for D	estinati	on Out o	f China's	Areas		10 11
3.7	7. F00RJ0)2130 Va	lve Asse	mbly's Pa	cking							11 11
4. F00F	7. F00RJ0 RJ02130 v pany Info	Valve Ass	embly's	Storage S	Standard			`				12
5. Com _l	pany Into I. Compa	rmation.	duction				100 m					13 13
5.2	1. Compa 2. Sales-m yright Sta	nen's Cor	itact Info	rmation				1				13
6. Copy	yright Sta	tement	34.c	94."	-94."	du.	Sur.	34	84	34	31	14
. osi	5	1	i andiel	S CONTRACT	S. Carlotte	Teams 1	Tellin.	Tribby I	1	t aggst	i and	gi Li
81/11	31/4	37,4	2000	6250	65000	differ.	811 m	811/10	811	977	2000	9300
	3 2000 - 13	Trippe P	1965.	i eggi	1	i in	i. Jagar	Tillian I	1965.	i men	S mili	ß.
Share	251,000	27,000	St.	2000	Office.	Starr.	21,000	21,000	Starte.	2000	Shippy.	250
	3 200	1		1	1	3 25	1		Data - P	1	3 .es	ß
SHUMST	SALMAN.	SPERMY.	SHEET STATE	SHOWER L	Stangert.	SHIPPE	SHIPPER	elginer.	SPERMEN.	i Shrani	SPECIFIC	\$1 ⁵⁵
			9 2	1	1 2	1		1	1			ď
sriving)	i Shumii	1 5/2.50/11	SPERMEN	SHEATHER	SPERMENT	SPERMIT	SPUMPY	SHUMAY.	SHUDAT	i Shranki	T SHELDIN	\$1 ⁸
				4 .	4 .						e .	ď
String.	SHAMA		SHELDHY	SPREERIN	SHRAMA	SPRINGER	SPLIDE	SHIPPET	SHUTHE	splant	SPERMIN	898
				_								_
SUNSE	SHAMA	1 5/1/2017		SHEETER	SHIME.	SINTERY.	SPERSON C	SH ^{AJON} S	SHIPPIN.	5171.5515.5	SHE SHE	51 ⁽²⁾
	201	.50.	30.	200	34	28.6	104.4	[50]	201	.Bu.	250.	1584
SH ^{LIMEN}			SHANNET E	SHARANI.	SHEARN.	SHOWER	SHAMMA	STANGET	SHE SHE'S		T SHAME	ji Seo
		927m	\$90m	200-	dit.	311	SM.	9W-	8877	537n-	200°°	910
- m ²	d	1	Peter.	Peters.	V Lager	Terror	i	Terrer 1	1	1 14664	S	S.

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd



F00RJ02130 Injector Valve Assembly Technical File

1. F00RJ02130 Injector Valve Assembly's Introduction

1.1. F00RJ02130 Injector Valve Assembly's Basic Information

		<u> </u>
	Title	China made brand new fuel injector valve assembly F00RJ02130
-6	SKU1	G1S8F00RJ02130
	SKU2	G1L10F00RJ02130/ L10000B2BJ02130
	The There	G1L10F00K30Z130/ L10000BZB30Z130
9	SKU3	G1L10F00RJ02130/ L10000B2BJ02130
		G1E1010010021307 E10000B2B302130
	SKU4	G1F2F00RJ02130/ F20000B2BJ02130
3	i., 34., 34.	24. 24. 24. 24. 24. 24. 24. 24. 24. 24.

1.2. F00RJ02130 Injector Valve Assembly's Application Information for Injectors

(1) F00RJ02130 Injector Valve Assembly's Car Model Matching Information

Injector Part Number	Car Model	OE Number	OE Number	OE Number		- 51		301
410m 41	CDC (CONSOLIDATED	2007 CO2005	21/0	3/m. 3	-3.	-3/0-		SV ^a
shim" st	DIESEL CO.) CUMMINS	397 6372 3 976 372	4 945 969	Strager S	Magain.	977 B	85. D. 980.	S0 ⁵
0.445.430.050			4 945 969		-	-		
0 445 120 059	CUMMINS	6754-11-3011	175 CO	(2077004)	10000000000000000000000000000000000000		21/2/2012 (2)	50 ⁽⁶⁾
0 445 120 060	COMMINIS	3 977 080	4 983 267	3977081	511	511	pn pn	000
SANDER.	DAF	1703934	orth conti	4.00	1. 100 m	00 a 0	A CONTRACTOR	- 18 C
5877 58	CUMMINS DONGFENG	4 937 065	300	811m. 81	311	88711	3000	500.
SPANIST'S	CUMMINS ENGINE (DCEC)	D4937065	en engliser.	sil ^{anari} s	ALEGE C.		ere Statistic	\$1 ²
0 445 120 123	TATA (TELCO)	570107999907	ort or	Lard.		3		
0 445 120 132	CUMMINS	4 945 381	Strainer.	Shipper S				30 ⁽²⁾
0 445 120 151	CUMMINS	4 981 128				_2		
0 445 120 152	CUMMINS	4 981 126	leg, "Filleg	-010 Bell 1	ndilletti i	roper .		
0 445 120 208	CUMMINS	5 254 688	72.1	7011	501	30	3	701
0 445 120 209	CUMMINS	5 254 682	arti marti	- ANDRES	NOTE OF	09 ¹⁵ 0	Million The	. 10.1
0 445 120 210	CUMMINS	5 254 686	-977-	55" 5	- 35	65	100	\$7.
0 445 120 211	CUMMINS	5 254 684	the the	P. Piller	- 18 Ban-	e 2000		
-St. St.	CASE	2830 957	2/000	8 S		180	30	8) ⁽⁰⁾
	CUMMINS	5 255 184	20 20			5	5	
State of	FORD	BG9X 9K526 BA	S. C.	al _{ner} a	19 Sales	m. App	330	314
0 445 120 212	VW (VOLKSWAGEN)	2R0 198 133	PALL SANTONIA	STANDALL S	4.3 ⁶⁶⁵		KITT SHEAT	98 ⁶
1	CUMMINS	5 263 262		_el		-2	-1	
0 445 120 231	KOMATSU	6754-11-3011	10 ⁹	- 1000	- 400	100 m	W. 1989	

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com



0 445 120 239	CUMMINS	5 263 312		Start Start	ri miriti	100 mg	60 me	
24 ₀₀₀ - 24	CUMMINS	5 263 316	Stephen Stephen	Storm	Stipe. Stipe	2/10	SASSA	51 ⁸
0 445 120 238	DODGE	5135 790AD	5135 790AB	05135 790AC	R5135790AF	05135 790AD	5135 790AC	05135 790AB
W-1	CUMMINS	5 263 321			West West			
0 445 120 250	TEMSA	5 263 321	100 P. Carlot	55°	C 2505 C 255	55 July 1	The state of the s	60
0 445 120 251	CUMMINS	5 263 314	-8r9r.	84.0	34., 34.,	347	98**	84.
0 445 120 252	CUMMINS	5 263 315	San Philips	St. mill	Constitution of	5 ⁴ 7	Trace Pa	
0 445 120 254	CUMMINS	5 263 317	alin, alin,	200	Sthree Sthree	2500	2000	5000
-2(1	CUMMINS	5 263 318	V 200	ect set	Trac 1	artii	rice in	
Shipper Sh	DODGE	5086 894AA	R8004082AC	05086 894AA	Shrips. Shrip	37,7500	275,000	43 ²
0 445 120 255	RAM	R8004082AC	5086 894AA	ord woods	The state of the s	priliti	Name of	. 6.1
0 445 120 256	CUMMINS	5 263 319	\$T" \$T"	ST	\$FT \$FT	200	\$577	2000
0 445 120 273	CUMMINS	5 263 307	i mili	O ^{rt} ort	i mari	95 ¹⁵	The section	
0 445 120 328	CUMMINS	5 273 750	5273750	21/02	240, 240,	:3100	\$X.	\$3 ⁷⁵
0 445 120 455	CUMMINS	5 367 161		- A	55	-3	en pro	



Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd



 $\mathcal{G}^{(i)}$

 $\mathcal{G}^{(0)}$

 $\otimes \mathcal{N}^{(i)}$

 $\leq h^{(k)}$

 $q\beta^{\prime\prime}$

 $\otimes^{(0)}$

(2) F00RJ02130 Injector Valve Assembly's Application for Injectors' Part Number

Injector Series	Injector Part Number	System Pressure	Re- manufactured Part Number	System Pressure	Universal Number	System Pressure	Universal Number
CRIN1-14/16	0 445 120 059		0 986 435 597	1600	0 445 120 231	1600	Arthur, Arthur
CRIN1-14/16	0 445 120 060	Stringer String	0 986 435 533	1600	0 445 120 250	1600	Walley Harring
CRIN1-14/16	0 445 120 123	1600	0 986 AD1 048	1600	0 445 120 123	DETT SHADATT	PERMITT SPERME
CRIN1-14/16	0 445 120 132	- m ^{g(1)} - mi	ri	T	arth agrith.	anti anti	- mi ^{rch} - mir
CRIN1-14/16	0 445 120 151 ₀ 0	ar ar	ar ar a	2 "44 24	0 445 120 239	1600	
CRIN1-14/16	0 445 120 152	31/10m 31/10m	3/10/2013	3/1/20 3/62	0 445 120 252	1600	Apple State
CRIN1-14/16	0 445 120 208	Strike Strike	0 986 435 505	1600	0 445 120 238	1600	Apple Shippe
CRIN1-14/16	0 445 120 209		0 986 435 575	elenger, elen	0 445 120 254	1600	F 00E 200 425
CRIN1-14/16	0 445 120 210	Shripper Shripe	0 986 435 503	1600	0 445 120 255	1600	Managar Shopping
CRIN1-14/16	0 445 120 211				SELL TOWNER, TO	MATERIAL .	4.500 ^{4.77}
CRIN1-14/16	0 445 120 212	1600	0 986 435 508	1400		211 3	
CRIN1-14/16	0 445 120 231	1600	0 986 435 597	1600	Sec. Marie Su	Walter Commence	Mary Straight
CRIN1-14/16	0 445 120 238	1600	0 986 435 505	1600	off off	-ari	-15T -15

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133



 $\varphi \beta^i$

 $\mathcal{G}^{(i)}$

 $\mathcal{G}_{i}^{(0)}$

 $\mathfrak{S}^{(0)}$

 $\otimes \mathcal{N}^{(i)}$

 $\otimes \ell^{(i)}$

 $g_{ij}^{(k)}$

CRIN1-14/16	0 445 120 239	1600	rs. Prs. Pr	r ser	art art	-15 -15		ď
CRIN1-14/16	0 445 120 250	1600	0 986 435 533	1600	57 ^A 580 S7	\$ 1 St. 1	A Strain Strain	
CRIN1-14/16	0 445 120 251	1600	Marine Things Th	T	officers that	The said	and the said	ξ.
CRIN1-14/16	0 445 120 252	1600	ale ale	97° 97°	\$1° \$1°	555,000	50m. 850m.	
CRIN1-14/16	0 445 120 254	1600	0 986 435 575	1600	F 00E 200 425	MALL RATINGLE		6
CRIN1-14/16	0 445 120 255	1600	0 986 435 503	1600	ANT WARRY OF	MARKET LEARNES	100 Miles	ď
CRIN1-14/16	0 445 120 256	1600	0 986 435 576	1600	F 00E 200 435		- 40 (4) - 40 (4)	e ⁻¹
CRIN1-14/16	0 445 120 273	1600	0 986 435 571	1600	500	5774	500	
	at Miles	antimis ^{ere} antimi	0 986 AD1 953	1600	OF THE STATE OF	NET STATE	3.11 ⁵⁵ 33.11 ⁶	
CRIN1-14/16	0 445 120 328	1600					6	
CRIN1-14/16	0 445 120 455	1600	Shipper Shipper	States, Alex	Strain, Sty	Mary Shippy	ASTON BASTON	

Mob/Whatsapp: +86 13410541523

Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

Tel: +8675523215133

(3) F00RJ02130 Injector Assembly Part Number Common Writing

F00RJ02130, F00RJ02130, F 00R J02 130, F 00R J02 130, F00RJ02 130, F00RJ02 130, F00RJ02 130, F00RJ02130, F 00RJ02130, F 00RJ0212130, F 00RJ0212120, F

1.3. F00RJ02130 Injector Valve Assembly's Specifications and Dimensions Parameters

Valve Assembly Size: 13 cm*2 cm *2 cm
Valve Assembly Box Size: 14 cm *3 cm *3 cm
Valve Assembly Packing Size: 31 cm *12 cm

Valve Assembly Net Weight: 0.03kg
Valve Assembly Gross Weight: 0.03kg

Valve Assembly Quality: China Made Brand New Injector Valve Assembly

Valve Assembly MOQ: 4 PCS

1.4. F00RJ02130 Injector Valve Assembly's Quality Control

(1) Valve Assembly Testing

All parts of the injector valve assembly are subjected to precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability testing, and various working conditions testing.

- Poss

(2) Injector Valve Assembly Inspection

The factory inspection of the injector valve assembly is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same injector valve assembly for a total of no less than three times for factory inspection, and the fuel injector installation testing environment are progressed in dust-free workshop.

(3) Injector Valve Assembly Installation

When matching the valve cap and valve steam, Shumatt strictly complies with the standard of valve cap and valve stem clearance technical indicators to ensure that each valve assembly meets the factory standards and use standards.

1.5. F00RJ02130 Injector Valve Assembly's Customized Service

(1) Valve Assembly's Customized Service: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, injector internal packaging, injector external packaging and labels customized, etc.

lettering, logo engraving, injector inte	mai packaging, injector external packa	ging and labels custoffized, etc.
8		245° 245° 245° 25
Valve Cap Color Customized 1000 pieces (White color is optional)	Valve Cap Color Customized 1000 pieces (Purple and red color are optional)	Valve Cap Groove Customized
	28.50 E	
Valve Cap Lettering、Valve Cap logo Engraving、Valve Cap QR Code Engraving	Valve Assembly Box (Square is optional)	Valve Assembly Box (Cylindrical is optional)

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: <u>ruby@shumatt.com</u> Website: <u>www.shumatt.com</u>





(2) Valve Assembly's Customized Service Requirements:

Customized valve assembly box are no less than 100 pieces.

Customized valve assembly groove no less than 100 pieces.

The purchased of customized valve assembly are no less than 1000 pieces.

The purchased of customized valve cap engraving contents are no less than 1000 pieces.

The purchased of customized valve colors are no less than between 1000 -10000 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

▲ Once the customized injector valve assembly is sold, it can not be returned or exchanged if there is no quality problems.

1.6. F00RJ02130 Injector Valve Assembly's Packing List

(1) Valve Assembly's spare parts list

	Assembly's spare parts list	<u>antilli antilli antilli antilli antilli</u>	
Serial Number	1	2	3 34. 34. 34.
Signal Principle Image	A Shumet	SW. 20	er an
SHIPPER SHIP	ent st	all ar ar all	
Name	Injector Valve Assembly	Valve Assembly Anti-rust Paper	Valve Assembly Box (Square is optional)
Description	Valve Assembly Part Number F00RJ02130	Prevent the valve assembly from rusting	Protect the valve assembly from being damaged by colliding
Serial Number	4	2 3400 3400	81 81 81 81.
المور Image	AT.	VC. VC.	THE SHEET SHEET SHEET SHE
SHALLINGER SHAL		Sh. Sh. Sh. Sh.	NA THEODELY THEODELY THEODELY
Name 	Valve Assembly Box (Cylindrical is optional)	VCI Anti-rust Bag	NT SANTON SANTON SANTON
Description	Protect the valve assembly from being damaged by colliding	Prevent the valve assembly from rusting	

- ▲ Minors are prohibited from using the injector valve assembly, valve assembly anti-rust paper, valve assembly box, and VCI anti-rust bag to avoid personal injury.
- The valve assembly box is recyclable and can be reused.
 - ▲ VCI anti-rust bag is non-degradable material, please dispose of it properly after use.

1.7. F00RJ02130 Injector Valve Assembly's Warranty Instructions

(1) . Valve Assembly Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the injector valve assembly inspection equipment when the valve assembly is abnormal during use as evidence to feed back to the

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



salesman.

Abnormal conditions are properly explained such as: 1. Smoke, 2. Engine shake, 3. Difficulty starting the engine, 4. Engine noise, 5. oil leakage etc.

(2) . Valve Assembly Warranty Coverage

Within 15 days after customer receives the F00RJ02130 injector valve assembly, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or repair أثابته أثابته

-85

If the F00RJ02130 injector valve assembly has performance problems during the warranty period (3 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free;

If the injector house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

(3) . Injector Valve Assembly Out of Warranty Coverage The warranty period has expired. THE PARTY SHEET THE PARTY.

45000

Injector valve assembly failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

Injector valve assembly damage caused by man-made reasons (throwing, strong magnetic field -Jag 100 P. V. magnetization, set fire). 1.500 Park

Injector valve assembly failure or injector damage caused by non-injector design, technology, manufacturing, quality and other issues.

Injector valve assembly failure due to system pressure exceeding system approved pressure.

Injector valve assembly failure caused by system voltage exceeding approved voltage.

Injector valve assembly failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector valve assembly failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

Injector valve assembly failure caused by not following the installation angle specified in the injector maintenance manual.

Injector valve assembly failure caused by not following the cleaning requirements specified in the injector maintenance manual.

Injector valve assembly failure caused by failure to replace consumable parts as specified in the injector maintenance manual.

1.8. F00RJ02130 Injector Valve Assembly's Manufacturer

Injector Valve Assembly's Manufacturer: Shenzhen Shumatt Technology Co.,Ltd

2. F00RJ02130 Injector Valve Assembly Technical Support


2.1. F00RJ02130 Injector Valve Assembly's Installation Precautions

- make the stains, dust, rust-proof oil oxides, paraffin base, naphthenic base, intermediate base, salt, lead naphthenate, zinc naphthenate, sodium patrologies and soldies. Clean the injector valve assembly in an ultrasonic cleaner for 3-5 minutes before installation, so as to calcium petroleum sulfonate, tallow diamine trioleate, rosin amine on the surface of the valve assembly fall off. -d0 ar Ch
 - Use compressed air to clean the cleaning fluid attached to the surface of the valve assembly after cleaning, and clean it up to the standard of use, as below
- (3) When installing the valve stem, make sure that the valve stem and the bonnet must ensure that the valve stem can move smoothly in it. as below


Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com





(4) When installing the valve stem, make sure that the valve stem and the bonnet must ensure that the valve stem can move smoothly in it. as below




If the injector steel ball and the ball seat are not installed in accordance with the standard, it may cause serious damage to the injector valve assembly

2.2. F00RJ02130 Injector Valve Assembly Replacement Conditions

(1) Valve Cap

Under the microscope, magnify 20 times to check that the oil inlet hole of the valve cap and the oil return hole of the bonnet are not worn, grooved, scratched, damaged, rusted or dented.



▲ The wear of the top oil return hole causes the oil return to be too large and the leaking injector cannot inject oil

▲ The side inlet hole is blocked causing the injector to establish the pressure chamber and the injector to function normally

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133


Email: <u>ruby@shumatt.com</u> Website: <u>www.shumatt.com</u>



Wear of the cap cavity can cause the injector to work properly when the injector is badly delayed.

(2) Valve Rod

Microscope amplification 20 times, check the valve rod for wear, not smooth surface color, rust



▲ The excessive clearance between the stem wear and the housing and between the cap causes an injector

▲ The valve stem lag will cause the injector to start the solenoid to start, and the oil needle can not return 9103 quickly after the nozzle is opened 900

▲ Check the injector components before replacing the injector valve assembly according following the injector service manual to avoid further damage to the injector valve assembly.

2.3. F00RJ02130 Valve assembly Technical Support Obtaining Methods

- (1) Valve assembly Technical file, visit http://shumatt.com to get the technical File
- (2) Injector Technical Videos

Facebook: Visit https://www.facebook.com/hison.li constantly follow can get more information.

YouTube: https://www.youtube.com/channel/UCByvYBx7VjV mAfxh Hu-aw to get the technical videos, constantly follow can get more information.

Shumatt: Visit http://shumatt.com to get the technical videos.

(3) Valve Assembly Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit http://shumatt.com to get the download and installation tutorial

(4) Search The valve assembly test data through TruckBook Parts EPC APP.

3. F00RJ02130 Valve Assembly's Purchase and Delivery.

3.1. F00RJ02130 Valve Assembly Purchase Payment Terms

Payment Terms: T/T, PayPal, Alipay, WeChat

Please contact our salesmen for specific payment information.

3.2. F00RJ02130 Valve assembly's Main Sales Market.

Valve assembly main sales markets: Asia, Europe, North America, South America, Africa etc.

3.3. F00RJ02130 Valve assembly's Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4. F00RJ02130 Valve Assembly's Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations out of China's areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5. F00RJ02130 Valve Assembly's Lead Time **Lead time:** Send out within 3 – 7 working days after receiving payment (Except for special products and special cases.) . The same of the same of

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133

Email: ruby@shumatt.com Website: www.shumatt.com



3.6. F00RJ02130 Valve Assembly's Logistics Time for Destination Out of China's Areas

DHL Logistics Time:

Country or Region of Departure	Hong Kong, China	Other Countries or Regions of Asia	Australia and New Zealand	Europe	America	Other Countries
China's Mainland	7 Days	7 Days	8 Days	8 Days	8-12 Days	7-10 Days

UPS Logistics Time: Country or Region of Departure: China's Mainland

Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time	Country of Destination	Estimated Arrival Time
Japan	3 Days	UK	5-7 Days	Egypt	5-7 Days
Turkey	5-7 Days	Singapore	3 Days	Switzerland	5- 7 Days
Bahrain	5-7 Days	Latvia	7-10 Days	New Zealand	7-10 Days
Sri Lanka	5-7 Days	Thailand	3 Days	Austria	5-7 Days
Romania	5-7 Days	Vietnam	3-5 Days	Estonia	5-7 Days
Malaysia	3-5 Days	Israel	5-7 Days	Mexico	7-10 Days
France	5-7 Days	America	5-7 Days	United Arab Emirates	5-7 Days
Italy	5-7 Days	Netherlands	5-7 Days	Bengal	7-10 Days
Lebanon	5-7 Days	Philippine	3-5 Days	Greece	7-10 Days
South Korea	3 Days	Spain	5-7 Days	Myanmar	5-7 Days
Canada	5-7 Days	Germany	5-7 Days	Saudi Arabia	7-10 Days
Portugal	5-7 Days	Australia	5-7 Days	South Africa	7-10 Days
Denmark	5-7 Days	Belgium	5-7 Days	Ukraine	7-10 Days
India	7-10 Days	Qatar	7-10 Days	Poland	5-7 Days
Indonesia Kuwait	3-5 Days 7-10 Days	Morocco	7-10 Days	Pakistan	7-10 Days

The logistics time is for reference only, subjects are according to the actual arrival.

3.7. F00RJ02130 Valve Assembly's Packing

Domestic express packaging: Usually wrapped in waterproof scotch tape, such as picture No.2.

International express packaging: Wrapped with waterproof yellow tape After wrapping the black protective film, such as picture No. 3.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 4, Also, the products can be packaged according to customers' requirements.

The packing tray is made of plastic and can be recycled.

A Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

A Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.


Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd





Pic No.1 **Domestic express packaging:**Wrapped by Transparent tape



Pic No.2

International express packaging:

Wrapped with yellow tape after wrapping black protective film



Pic No.3

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

4. F00RJ02130 Valve Assembly's Storage Standard

(1) Choose a suitable storage place

The warehouse and cargo yard where the fuel injector is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry.

(2) Strict requirements of warehousing

Strict inspections should be carried out when the fuel injectors are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do antirust treatment in time. Packaged injectors must be protected from damage.

(3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for the fuel injectors placed in the room, and the corrosion of the fuel injectors is significantly reduced.

Injectors must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content.

(4) Stack Properly

After the injector is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com



is to isolate the injector from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

If the fuel injector package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

It is forbidden to leave the injector exposed in the air for a long time.

It is forbidden to store acid, alkali, salt and other substances together with the injector.

The unpacked fuel injector must be rust-proof during secondary storage.

5. Company Information



5.1. Company Introduction

Chinese Name: 深圳市舒马特科技有限公司

English Name: Shenzhen Shumatt Technology Co., Ltd

Mob Phone/WeChat: +86-13410541523

HK Telephone: +852-67653519
Telephone: +86-755-23215133
Email: ruby@shumatt.com
Website: www.shumatt.net

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station,

Bao'an District, Shenzhen, China's Mainland

Shenzhen Office: Room 428-430, Building B, Huafeng Zhigu Technology Industrial Park, Exit B, Fuyong Metro

Station, Bao'an District, Shenzhen, China's Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: 1.7. F00RJ02130 Injector Valve Assembly's Warranty Instructions)

5.2. Sales-men's Contact Information

0										
No.	Name	WeChat/ WhatsApp	Email	Facebook	YouTube					
1	Ruby	+86-13410541523	ruby@shumatt.com	Hison Li	Hison Li					
2	lvv	+86-18025309821	sales@shumatt.com	lyy Shumatt	Shumatt IVV					

Mob/Whatsapp: +86 13410541523 Tel: +8675523215133
Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd


13 / 14



3	Rebecca	+86-18025349821 sales01@shumatt.com		Rebecca SHUMATT	SHUMATT Rebecca
4	Janny	+86-18028749821	sales02@shumatt.com	Janny shumatt	Janny Shumatt
5,40	Sam	+86-13316859821	Sales8@shumatt.com	Shumatt Sam	Sam Shumatt
6	Natalie	+86- 18938945856	sales15@shumatt.com	Shumatt Natalie	Lin Natalie
7	Ada +86-1342286353 sales		sales5@shumatt.com	Shumatt Ada	Ada Shumatt
8	Hison Li	+86-18318811871	web@shumatt.com	Hison Li	Hison Li
9	Mecca	+86-18938948618	sales11@shumatt.com	Shumatt Mecca	Shumatt Mecca
10	Eric	+86 18319033618	sales3@shumatt.com		
11	Wayne (Joaquín en español)	+86-13316959821	wayne@shumatt.com	shumattwayne	Wayne Shumatt
12	Sylvia	+86 18312499884	sales6@shumatt.com	800mg	2000 - 2000
·	Vis	ii http://shumatt.com	o obtain the latest information of sal	es-men	

6. Copyright Statement

The copyright of any contents "FOORJO2130 valve assembly technical fail" (including but not limited to parameters, data, text, charts, images, sounds or videos, etc.) provided in "FOORJO2130 Valve assembly Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "FOORJO2130 Valve assembly Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "FOORJO2130 Valve assembly Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "F00RJ02130 Valve assembly Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.



Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 Email: ruby@shumatt.com Website: www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

14 / 14