



Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com

F00RJ02806 Injector Valve Assembly Technical File

2.F00RJ02806 Injector Valve Assembly Technical Support 2.3.F00RJ02806 Valve assembly Technical Support Obtaining Methods. 3.2.F00RJ02806 Valve assembly's Main Sales Market. 3.4.F00RJ02806 Valve Assembly's Shipping Ways9 4.F00RJ02806 Valve Assembly's Storage Standard 11 5.2. Sales-men's Contact Information...... 12

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd F00RJ02806 Injector Valve Assembly Technical File

 $\mathfrak{P}^{\mathbb{N}}$

1. F00RJ02806 Injector Valve Assembly's Introduction

1.1.F00RJ02806 Injector Valve Assembly's Basic Information

| Title | China made brand new fuel injector valve assembly F00RJ02806 | | | | | |
|--------------|---|--|--|--|--|--|
| SKU1 | G1S8F00RJ02806 | | | | | |
| SKU2 | G1F1F00RJ02806/F10000B2BJ02806 | | | | | |
| SKU3 | G1F2F00RJ02806/F20000B2BJ02806 (High quality) | | | | | |
| 12 500010200 | and the second ble same bear a family and a family second by the second s | | | | | |

1.2.F00RJ02806 Injector Valve Assembly's Application Information for Injectors (1) F00RI02806 Injector Valve Assembly's Car Model Matching Information

| Injector Part Number | Car Number | OE Number | OE Number | OE Number |
|----------------------|-----------------------------------|--------------------|------------------|---------------|
| 0 445 120 083 | YUCHAI MACHINERY | G2100-1112100-A38 | | |
| 0 445 120 110 | YUCHAI MACHINERY | J5600-1112100-A38 | 13.5000 - 13.500 | ALL THERE |
| 0 445 120 156 | YUCHAI MACHINERY | L4700-1112100-A38 | 20. 20. | |
| 0 445 120 164 | YUCHAI MACHINERY | A6000 1112100 A38 | all all | C . Martin |
| 0 445 120 225 | YUCHAI MACHINERY | G1000-1112100-A38 | 34 34 | 34 34 |
| 0 445 120 290 | YUCHAI MACHINERY | L4700-1112100A-A38 | | 6 |
| 0 445 120 291 | YUCHAI MACHINERY | J0100-1112100A-A38 | Show Show | store ste |
| 0 445 120 292 | YUCHAI MACHINERY | J6A00-1112100-A38 | | |
| 0 445 120 293 | YUCHAI MACHINERY | A6A00-1112100-A38 | All All | A. Car |
| 0 445 120 304 | CUMMINS | 5 272 937 | - <u>-</u> | |
| 0 445 120 377 | DCEC (DONGFENG CUMMINS ENGINE) | C5307809 | Struggler Strugg | Stranger Str. |
| 0 445 120 381 | YUCHAI MACHINERY | EG200-1112100-A38 | | a a |
| 0 445 120 419 | YUCHAI MACHINERY | LVA00-1112100-A38 | and and and | dell' de |
| 0 445 120 439 | - <u>20</u> 30 3 | - 30 - 30 | 201 201 | 201 201 |

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd

de



SPREAME

SA.M

(2) F00RJ02806 Injector Valve Assembly's Application for Injectors' Part Number

| Injector Series | Injector Part Number | System Pressure | Re-manufactured Part Number | System Pressure | Universal Number | System Pressure | Universal Number | System Pressure |
|---------------------------|----------------------|---------------------------|--------------------------------|--------------------|---------------------|--------------------|---------------------|--------------------|
| | | Pressure | Number | Pressure | 0 445 120 | Pressure | Number | Pressure |
| CRIN2-16 | 0 445 120 083 | 1600 | 0 986 AD1 036 | 1600 | 443 120 | 1600 | | |
| | | | | | 0 445 120 | | 0 445 120 | |
| CRIN2-16 | 0 445 120 110 | | 0 986 AD1 037 | 1600 | 292 | 1600 | 437 | 1600 |
| | | | | | | | | |
| CRIN2-16 0 445 120 156 | | 0 986 AD1 038 | 1600 | 0 445 120 | 1600 | 0 445 120 | 1600 | |
| | | | | | 290 | | 434 | |
| CRIN2-16 | 0 445 120 164 | 1600 | 0 986 AD1 040 | 1600 | | | | |
| CRIN2-16-BL | 0 445 120 225 | 1600 | | | 0 445 120 439 | 1600 | | |
| CRINZ-10-DL | 0 445 120 225 | 1600 | | | | 1600 | | |
| | 0.445.420.200 | 0 445 120 290 1600 | 0 986 AD1 038 | 1600 | 0 445 120 | 1600 | | |
| CRIN2-16-BL | 0 445 120 290 | | | | 434 | | | |
| | 0.445.400.004 | 445 120 291 1600 | | | 0 445 120 | 1600 | | |
| CRIN2-16-BL | 0 445 120 291 | | | | 438 | | | |
| | | 0 445 120 292 1600 | 0 986 AD1 037 | 1600 | 0 445 120 | 1600 | | |
| CRIN2-16-BL 0 445 120 292 | 0 445 120 292 | | | | 437 | | | |
| | | 0 445 120 293 1600 | | | 0 445 120 | 1600 | | |
| CRIN2-16-BL | 0 445 120 293 | | | | 435 | | | |
| CRIN2-16-BL | 0 445 120 304 | 1600 | | | | | | |
| CRIN2-16-BL | 0 445 120 377 | 1600 | | | | | | |
| | | | | | 0 445 120 | | | |
| CRIN2-16-BL | 0 445 120 381 | 1600 | | | 428 | 1600 | | |
| CRIN2-16-BL | 0 445 120 419 | 1600 | | | | | | |

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com Tel: +8675523215133 Website : www.shumatt.com

© 2022 Shenzhen Shumatt Technology Co., Ltd

 $S^{(i)}$

3 / 13

<u>2</u>8.20577 SPARAT Shenzhen Shumatt Technology Co., Ltd SHUMATT $\sim 10^{10}$ 0 445 120 0 445 120 439 1600 CRIN2-16-BL 1600 225 SPURAT SPUTT $\mathcal{D}^{(0)}$ SPUDDIC $\mathcal{G}_{i}^{(0)}$ SHUDDAL $\otimes^{\mathbb{N}}$ SPATIST ${\rm S}^{(i)}$ SPANNET SPUIDET $\wp_i^{\otimes_i}$ SPLIDET $\otimes_{i}^{\otimes_{i}}$ -stutters State. $\mathcal{Q}^{(0)}_{i}$ SHUDDI $\otimes^{\mathbb{N}}$ SHADAT 518203777 Mob/Whatsapp: +86 13410541523 Tel: +8675523215133 $e^{\frac{1}{2} \frac{1}{2}}$ Website : <u>www.shumatt.com</u> Email : ruby@shumatt.com $\mathcal{G}^{(i)}$

 $\otimes^{[0]}$

© 2022 Shenzhen Shumatt Technology Co., Ltd

COLORATE S

THE REAL PROPERTY.

-A.B.ST

-ALTERN'

SAMONT'S

THE REAL PROPERTY.

COLORATE .

(3) F00RJ02806 Injector Assembly Part Number Common Writing

1.3.F00RJ02806 Injector Valve Assembly's Specifications and Dimensions Parameters

Valve Assembly Size: 13 cm*2 cm *2 cm

Valve Assembly Box Size: 14 cm *3 cm *3 cm

Valve Assembly Packing Size: 31 cm *12 cm

Valve Assembly Net Weight: 0.03kg

Valve Assembly Gross Weight: 0.03kg

Valve Assembly Quality: China Made Brand New Injector Valve Assembly

Valve Assembly MOQ: 4 PCS

1.4.F00RJ02806 Injector Valve Assembly's Quality Control

(1) Valve Assembly Testing

All parts of the injector valve assembly are subjected to precision testing, high temperature testing, low temperature testing, withstand pressure testing, leakage testing, durability testing, and various working conditions testing.

(2) Injector Valve Assembly Inspection

The factory inspection of the injector valve assembly is undergone full inspection, random inspection, and batch inspection three inspections. Different brands of test benches are used to test the same injector valve assembly for a total of no less than three times for factory inspection, and the fuel injector installation testing environment are progressed in dust-free workshop.

(3) Injector Valve Assembly Installation

When matching the valve cap and valve steam, Shumatt strictly complies with the standard of valve cap and valve stem clearance technical indicators to ensure that each valve assembly meets the factory standards and use standards.

1.5.F00RJ02806 Injector Valve Assembly's Customized Service

(1) Valve Assembly's Customized Service: Meet the customized needs of OEM manufacturers for shell lettering, logo engraving, injector internal packaging, injector external packaging and labels customized, etc.



Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd



(2) Valve Assembly's Customized Service Requirements:

Customized valve assembly box are no less than 100 pieces.

Customized valve assembly groove no less than 100 pieces.

The purchased of customized valve assembly are no less than 1000 pieces.

The purchased of customized valve cap engraving contents are no less than 1000 pieces.

The purchased of customized valve colors are no less than between 1000 -10000 pieces.

Customized products involve the need of specify logo, the OEM manufacturer needs to provide trademark authorization and the sample of logo image file.

A Once the customized injector valve assembly is sold, it can not be returned or exchanged if there is no quality problems.

1.6.F00RJ02806 Injector Valve Assembly's Packing List

| (1) Valve | Assembly's spare parts list | and all all all all | an anal and and and |
|-----------------------------------|---|--|--|
| Serial Serial Number | 31 31 31 1 | 2 | 3 ST ST ST |
| State State | Charles and the second | 51 ^{11,077} 51 ^{11,07} | 8 ⁷⁵ 87 8 8 |
| and and all | 18 | et er er et | |
| Name | Injector Valve Assembly | Valve Assembly Anti-rust Paper | Valve Assembly Box (Square |
| Description | Valve Assembly Part Number F00RJ02806 | Prevent the valve assembly from rusting | Protect the valve assembly from being damaged by colliding |
| Serial Number | st st st | s ^{er} 5 ^{ser} s ^{er} | Str. 31. 31. 31. |
| SHUDATT SH Image SHUDATT SH | | | ALL SATURLE SATURLE SATURLE SA V SATURLE SATURLE SATURLE SA |
| Name | Valve Assembly Box (Cylindrical is optional) | VCI Anti-rust Bag | |
| Description | Protect the valve assembly from being damaged by colliding | Prevent the valve assembly from rusting | |

▲ Minors are prohibited from using the injector valve assembly, valve assembly anti-rust paper, valve assembly box, and VCI anti-rust bag to avoid personal injury.

The valve assembly box is recyclable and can be reused.

VCI anti-rust bag is non-degradable material, please dispose of it properly after use.

1.7.F00RJ02806 Injector Valve Assembly's Warranty Instructions

(1) . Valve Assembly Warranty Conditions and Instructions

It is necessary to provide pictures, videos, or test reports detected by the injector valve assembly inspection equipment when the valve assembly is abnormal during use as evidence to feed back to the

salesman.

Abnormal conditions are properly explained such as: 1.Smoke, 2. Engine shake, 3. Difficulty starting States -28-15¹⁷ the engine, 4. Engine noise, 5. oil leakage etc.

(2) . Valve Assembly Warranty Coverage

Within 15 days after customer receives the FOORJ02806 injector valve assembly, if there is a performance failure and the product has no appearance damage, customer can choose to replace it or The repair it; 15 N

æÖ.

150

If the F00RJ02806 injector valve assembly has performance problems during the warranty period (3 months), and it is confirmed that it is product's problems after testing, you can contact our salesmen to replace the same model or a reworked product with the same performance for free; de Ca

If the injector house has obvious scratches, it can only be repaired and it will be returned as it is if the product is confirmed to be fault-free.

STREET. Then Then and a contract and the STORY .

(3) . Injector Valve Assembly Out of Warranty Coverage The warranty period has avoired

The warranty period has expired.

Injector valve assembly failure caused by high temperature, high pressure, humidity, rain and snow, saline-alkali land, earthquake, and used in abnormal environment.

Injector valve assembly damage caused by man-made reasons (throwing, strong magnetic field 33090 AND PR magnetization, set fire).

Injector valve assembly failure or injector damage caused by non-injector design, technology, manufacturing, quality and other issues.

Injector valve assembly failure due to system pressure exceeding system approved pressure.

Injector valve assembly failure caused by system voltage exceeding approved voltage.

Injector valve assembly failure caused by impurities (water, lead, aluminum powder, iron powder, sulfide) in the system fuel exceeding the standard requirements.

Injector valve assembly failure caused by not installing according to the tightening torque specified in the vehicle engine maintenance manual (the tightening torque is too large or too small).

Injector valve assembly failure caused by not following the installation angle specified in the injector maintenance manual.

Injector valve assembly failure caused by not following the cleaning requirements specified in the injector maintenance manual.

Injector valve assembly failure caused by failure to replace consumable parts as specified in the SPRINGER injector maintenance manual. 39.00

1.8.F00RJ02806 Injector Valve Assembly's Manufacturer


Injector Valve Assembly's Manufacturer: Shenzhen Shumatt Technology Co.,Ltd

2.F00RJ02806 Injector Valve Assembly Technical Support

2.1.F00RJ02806 Injector Valve Assembly's Installation Precautions

- -5A-157F to make the stains, dust, rust-proof oil oxides, paraffin base, naphthenic base, intermediate base, salt, lead naphthenate, zinc naphthenate, sodium netrolection is the state of the state Clean the injector valve assembly in an ultrasonic cleaner for 3-5 minutes before installation, so as sulfonate, calcium petroleum sulfonate, tallow diamine trioleate, rosin amine on the surface of the valve assembly fall off. 1000 de. 120 de la d Chi 10 B
- (2) Use compressed air to clean the cleaning fluid attached to the surface of the valve assembly after cleaning, and clean it up to the standard of use, as below , an تا 1975

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2022 Shenzhen Shumatt Technology Co., Ltd



If the injector steel ball and the ball seat are not installed in accordance with the standard, it may cause serious damage to the injector valve assembly

2.2.F00RJ02806 Injector Valve Assembly Replacement Conditions

(1) Valve Cap

Under the microscope, magnify 20 times to check that the oil inlet hole of the valve cap and the oil return hole of the bonnet are not worn, grooved, scratched, damaged, rusted or dented.




inject oil

68⁵⁸ The side inlet hole is blocked causing the injector to establish the pressure chamber and the injector to function normally

A Wear of the cap cavity can cause the injector to work properly when the injector is badly delayed.

(2) Valve Rod

Microscope amplification 20 times, check the valve rod for wear, not smooth surface color, rust



replaced

▲ The excessive clearance between the stem wear and the housing and between the cap causes an injector delay

▲ The valve stem lag will cause the injector to start the solenoid to start, and the oil needle can not return quickly after the nozzle is opened

• Check the injector components before replacing the injector valve assembly according following the injector service manual to avoid further damage to the injector valve assembly.

2.3.F00RJ02806 Valve assembly Technical Support Obtaining Methods

(1) Valve assembly Technical file, visit <u>http://shumatt.com</u> to get the technical File
(2) Injector Technical Videos

Facebook: Visit <u>https://www.facebook.com/hison.li</u> constantly follow can get more information. **YouTube:** <u>https://www.youtube.com/channel/UCByvYBx7VjV_mAfxh_Hu-aw</u> to get the technical videos, constantly follow can get more information.

Shumatt: Visit <u>http://shumatt.com</u> to get the technical videos.

(3) Valve Assembly Information Query Software

TruckBook Parts EPC APP, Android/Apple App Store download and install, visit <u>http://shumatt.com</u> to get the download and installation tutorial

(4) Search The valve assembly test data through TruckBook Parts EPC APP.

3.F00RJ02806 Valve Assembly's Purchase and Delivery.

3.1.F00RJ02806 Valve Assembly Purchase Payment Terms

Payment Terms: T/T, PayPal, Alipay, WeChat

Please contact our salesmen for specific payment information.

3.2.F00RJ02806 Valve assembly's Main Sales Market.

Valve assembly main sales markets: Asia, Europe, North America, South America, Africa etc.

3.3.F00RJ02806 Valve assembly's Declaration Requirements

Shumatt can assist customers to provide the following documents for import customs clearance: contract, invoice, packing list, bill of lading, insurance policy, certificate of origin, etc.

3.4.F00RJ02806 Valve Assembly's Shipping Ways

Destination in China areas: SF Express, Debon Express, the corresponding logistics company can be provided according to customer requirements in special cases.

Destinations out of **China's** areas: DHL, UPS, FedEx, TNT air, ocean or other shipping methods required by customers.

3.5.F00RJ02806 Valve Assembly's Lead Time

Lead time: Send out within 3 - 7 working days after receiving payment (Except for special products and special cases).

3.6.F00RJ02806 Valve Assembly's Logistics Time for Destination Out of China's Areas

 $S^{(1)}$

SHUMATT **DHL Logistics Time:**

| Country or Region of Departure | Hong Kong, China | Other Countries or Regions of Asia | Australia and New Zealand | Europe | America | Other Countries |
|-----------------------------------|---------------------|---------------------------------------|------------------------------|--------|-----------|--------------------|
| China's Mainland | 7 Days | 7 Days | 8 Days | 8 Days | 8-12 Days | 7-10 Days |

| Country of Destination | Estimated Arrival Time | Country of Destination | Estimated Arrival Time | Country of Destination | Estimated Arrival Time |
|---------------------------|---------------------------|------------------------|---------------------------|------------------------|---------------------------|
| Japan | 3 Days | UK | 5-7 Days | Egypt | 5-7 Days |
| Turkey | 5-7 Days | Singapore | 3 Days | Switzerland | 5-7 Days |
| Bahrain | 5-7 Days | Latvia | 7-10 Days | New Zealand | 7-10 Days |
| Sri Lanka | 5-7 Days | Thailand | 3 Days | Austria | 5-7 Days |
| Romania | 5-7 Days | Vietnam | 3-5 Days | Estonia | 5-7 Days |
| Malaysia | 3-5 Days | Israel | 5-7 Days | Mexico | 7-10 Days |
| France | 5-7 Days | America | 5-7 Days | United Arab Emirates | 5-7 Days |
| Italy | 5-7 Days | Netherlands | 5-7 Days | Bengal | 7-10 Days |
| Lebanon | 5-7 Days | Philippine | 3-5 Days | Greece | 7-10 Days |
| South Korea | 3 Days | Spain | 5-7 Days | Myanmar | 5-7 Days |
| Canada | 5-7 Days | Germany | 5-7 Days | Saudi Arabia | 7-10 Days |
| Portugal | 5-7 Days | Australia | 5-7 Days | South Africa | 7-10 Days |
| Denmark | 5-7 Days | Belgium | 5-7 Days | Ukraine | 7-10 Days |
| State India State | 7-10 Days | Qatar | 7-10 Days | Poland | 5-7 Days |
| Indonesia | 3-5 Days | Morocco | 7-10 Days | Pakistan | 7-10 Days |
| Kuwait | 7-10 Days | the state states | alter alter | all the all the all | an start |

The logistics time is for reference only, subjects are according to the actual arrival.

3.7.F00RJ02806 Valve Assembly's Packing

Domestic express packaging: Usually wrapped in waterproof scotch tape, such as picture No.2. International express packaging: Wrapped with waterproof yellow tape After wrapping the black S. A. STR. protective film, such as picture No. 3.

Pallet Shipping: Use fumigation free and recycling trays that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties for the outside, such as picture No. 4, Also, the products can be packaged according to customers' requirements. -31598 A.S.

A The packing tray is made of plastic and can be recycled.


STA. Transparent tape, yellow tape, black wrapping protective film, white wrapping protective film are non-degradable materials, please dispose of them properly.

Minors are prohibited from using transparent tape, yellow tape, black wrapping protective film, and white wrapping protective film to avoid personal injury.









Pic No.2 Domestic express packaging: Wrapped by Transparent tape

Pic No.3 International express packaging: Wrapped with yellow tape after wrapping black protective film



Pic No.4

Pallet Shipping: Use pallet that meet export requirements, and use white wrapping protective film to wrap and bind with cable ties

-TRADET SHI STORY S12.578 4.F00RJ02806 Valve Assembly's Storage Standard

(1) Choose a suitable storage place

100 The warehouse and cargo yard where the fuel injector is stored should be kept clean and dry, and away from the factory buildings that generate harmful gases and dust; do not mix with acid, alkali, salt and other substances; the storage place should have a good drainage system; the cargo yard should be flattened with gravel or furnace ash etc. to enhance the water permeability of the surface layer to keep the reservoir area dry. at the

(2) Strict requirements of warehousing

and the Strict inspections should be carried out when the fuel injectors are put into storage, the surface cleaning work should be done well to remove water traces, oil stains, ash and other dirt, remove the rust and do anti-rust treatment in time. Packaged injectors must be protected from damage.

(3) Keep the warehouse dry and preventing moisture

The relative humidity is usually below 70% for the fuel injectors placed in the room, and the corrosion of the fuel injectors is significantly reduced.

Injectors must be stored in the warehouse, and they are forbidden to store in the same warehouse with commodities with high water content. The The States The States The States

(4) Stack Properly

Mob/Whatsapp: +86 13410541523 Email : ruby@shumatt.com © 2022 Shenzhen Shumatt Technology Co., Ltd

After the injector is exposed to rain, the corrosion rate will increase significantly. The purpose of sealing is to isolate the injector from rainwater and humid air, so the warehouse window should be checked in time to avoid rainwater entering the warehouse

If the fuel injector package is damaged, it should be repaired or replaced; when the package is damp, the packaging material should be dried; if the original anti-corrosion and oil applied at the factory is found to be damaged or dried up, it should be cleaned and re-applied oil in time.

It is forbidden to leave the injector exposed in the air for a long time.

It is forbidden to store acid, alkali, salt and other substances together with the injector.

The unpacked fuel injector must be rust-proof during secondary storage.

5. Company Information

 3^{0}



Telephone: +86-755-23215133

Email: ruby@shumatt.com

Website: www.shumatt.net

Shenzhen Office: 11-12, Floor 14, Building 13, Qinchengda Building, Exit A, Honglang North Subway Station, Bao'an District, Shenzhen, China's Mainland

Shenzhen Office: Room 428-430, Building B, Huafeng Zhigu Technology Industrial Park, Exit B, Fuyong Metro Station, Bao'an District, Shenzhen, China's Mainland

Hong Kong Office: Jianfa Street Industrial Zone, Tuen Mun, New Territories, Hong Kong, China

After-sales Service Address: Please contact our salesmen to obtain and provide the corresponding product maintenance reasons (Reference: <u>1.7.F00RJ02806 Injector Valve Assembly's Warranty Instructions</u>)

5.2. Sales-men's Contact Information

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : <u>www.shumatt.com</u>

| 1 | Ruby | +86-13410541523 | ruby@shumatt.com | Hison Li | Hison Li |
|-----------------------|--------------------------------|------------------|---------------------|--------------------|---|
| 2 | lvy | +86-18025309821 | sales@shumatt.com | Ivy Shumatt | Shumatt IVY |
| 3 33 ⁰⁰ | Rebecca | +86-18025349821 | sales01@shumatt.com | Rebecca SHUMATT | SHUMATT Rebecca |
| 4 | Janny | +86-18028749821 | sales02@shumatt.com | Janny shumatt | Janny Shumatt |
| 5 | Sam | +86-13316859821 | Sales8@shumatt.com | Shumatt Sam | Sam Shumatt |
| 6 . 0 | Natalie | +86- 18938945856 | sales15@shumatt.com | Shumatt Natalie | Lin Natalie |
| 7 | Ada 🖌 | +86-1342286353 | sales5@shumatt.com | Shumatt Ada | Ada Shumatt |
| 8 | Hison Li | +86-18318811871 | web@shumatt.com | Hison Li | Hison Li |
| 9 | Mecca | +86-18938948618 | sales11@shumatt.com | Shumatt Mecca | Shumatt Mecca |
| 10 | Eric | +86 18319033618 | sales3@shumatt.com | de de | 1997 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - 1998 - |
| 11 | Wayne (Joaquín en español) | +86-13316959821 | wayne@shumatt.com | shumattwayne | Wayne Shumatt |
| 12 | Sylvia | +86 18312499884 | sales6@shumatt.com | n - 192 - 19 | Par Pa |

6. Copyright Statement

The copyright of any contents "FOORJO2806 valve assembly technical file" (including but not limited to parameters, data, text, charts, images, sounds or videos, etc.) provided in "FOORJO2806 Valve assembly Technical File" belong to Shenzhen Shumatt Technology Co., Ltd. Without the prior written permission of Shenzhen Shumatt Technology Co., Ltd., you are not allowed to modify any contents in "FOORJO2806 Valve assembly Technical File" in any way. At the same time, any conditions to spread, re-post, display the contents of "FOORJO2806 Valve assembly Technical File" should indicate that the cited article is from Shenzhen Shumatt Technology Co., Ltd., Any actions failure to follow above conditions to use "FOORJO2806 Valve assembly Technical File" will violate the "Copyright Law of the People's Republic of China" and other laws and regulations and the provisions of relevant international conventions.

9^{9,518}

 $\otimes^{\mathbb{N}}$

Mob/Whatsapp: +86 13410541523 Email : <u>ruby@shumatt.com</u> © 2022 Shenzhen Shumatt Technology Co., Ltd Tel: +8675523215133 Website : www.shumatt.com